
Conical K-Lock





	CONICAL K-LOCK NUTS FASTENERS SAE J238												AE J238
		F		С	N		w		T	H		R	
Nominal Size or Basic Thread Diameter		Across the Flats		Across Corners	Nut Height		Washer Diameter		Washer Material Thick- ness	Full Assembly Height		Washer Rim Width	
	0	Max	Min	Min	Max	Min	Max	Min	Ref	Max	Min	Max	Min
4	0.1120	.250	.241	.272	.098	.092	.333	.323	.015	.150	.130	.015	.010
6	0.1380	.312	.302	.344	.098	.092	.333	.323	.015	.150	.130	.015	.010
8	0.1640	.344	.332	.378	.130	.117	.380	.370	.030	.195	.170	.015	.010
10	0.1900	.376	.362	.410	.130	.117	.408	.395	.020	.195	.170	.015	.010
1/4	0.2500	.438	.423	.482	.130	.117	.506	.494	.025	.195	.170	.015	.010
5/16	0.3125	.500	.489	.557	.195	.180	.569	.555	.030	.265	.240	.020	.015
3/8	0.3750	.562	.551	.628	.227	.210	.632	.618	.030	.300	.260	.020	.015



Description	A hex nut pre-assembled with a free-spinning conical washer. A high tension is maintained in the screw and nut assembly as the nut is tightened against the bearing surface.					
Applications / Advantages	Having the washer pre-assembled with the nut shortens installation time. Conical washer assemblies can compensate for joint contraction and expansion and can span slightly oversized holes.					
Material	Nuts: Shall be made from a low carbon steel that conforms to the following chemical composition: Carbon: 0.47% max.; Phosphorous: 0.12% max.; Sulfur: 0.15% max. Washers: SAE 1050 - 1065 carbon steel, fabricated and heat-treated					
Hardness	Nuts: No. 4 thru #12 diameter: No standard applies 1/4" and larger: Rockwell HRC 32 maximum Washers: Rockwell C 44 - 48 Rockwell C 46 - 50 (when austempering process is used)					
Plating	Nuts are usually supplied with a zinc or black oxide finish. See Appendix-A for more information.					

